

Dec. 11, 2019

Product Bulletin # TM-029 v 1.0

# TM120 v1.3 Upgrade Available


Canrig has issued a kit to upgrade the Canrig® Torq-Matic™ Automated Wrench from version 1.2 to version 1.3. This upgrade includes several improvements on performance and reliability. See below for a summary of new features. Contact your Account Representative or RIGLINE 24/7™ to order this kit.

Qty	Canrig P/N	Description
1	AY51476	KIT, UPGRADE, TM120 V1.2 TO V1.3

# Implemented Upgrades


### 1. Spinner Assembly

#### 1.1. Link Arm



• Changed material to A514 GR B to reduce buckling.

#### 1.2. Link Arm Pins




- Replaced threaded pin with a straight drop pin that is installed from the top of the traveling frame.
- Pin material upgraded to higher yield strength steel. Rear pin redesigned to eliminate the many stress concentration points. Pin is now straight.




Dec. 11, 2019

### 1.3. Link Arm Support Plate



• Added support plate to reinforce link arm and mitigate buckling.

## 1.4. Side Arm Stopping Plate




• Added a mechanical stop to prevent the spinner roller frame from colliding with hydraulic cylinder.



Dec. 11, 2019


#### 1.5. Pins




- Added Bondura pins to prevent weldment deformation and pin failures.
- Added greaseless polygon bushings (No lubrication needed).

### 2. Remote I/O and Arm Box Guard

#### 2.1. Remote I/O





- Eliminated 37-pin cable to reduce failure and troubleshooting time.
- Added additional functionality/automation.



Dec. 11, 2019


#### 2.2. Box Guard






- Arm box guard re-designed to be more robust and serviceable.
- Created second guard for new remote I/O setup.

## 3. Proximity Sensor



• Improved proximity sensor cover and target bar design.

## 4. Encoder Cap




 Changed material from composite to metal (AISI 1045) to reduce encoder failure due to cap breaking.



Dec. 11, 2019


## 5. Non-Bypass Filter




• Changed to a non-bypass filter to avoid contamination in the TM hydraulic system.

### 6. Arm Assembly

#### 6.1. Rear Bondura Pin



#### 6.2. Front Bondura Pin




• Changed to Bondura pin. New pin is stronger, larger, and improves serviceability.



Dec. 11, 2019


## 7. Torque Assembly

### 7.1. Jeep Support Bracket and Vertical Lift Mount



- 1. Added protective guard for hydraulic fitting and jeep support bracket.
- 2. Updated vertical mount and hardware to retain center of gravity on torque assembly.

### 7.2. Jaw Assembly




• Using TM80 v1.3 improved die retainment for longer life.



Dec. 11, 2019

## 8. Cylinders



- Integrated internal LVDT and counter-balance valve into extension cylinder (1).
- Integrated internal LVDT for torque cylinder (1 & 2).
- Added greaseless polygon bushings w/wiper seals (all cylinders).
- Improved reliability (all cylinders).