

GB and TC Input Shaft Inspection

The current brake system configuration lacks brake modulation to avoid high load shock during brake set. If brakes are applied too fast, gearbox gears and snap rings can become damaged.

The gearbox input shaft may move axially approximately $\frac{1}{2}$ – $\frac{3}{4}$ inch, shearing off or popping out the retaining rings and causing the transfer case output gear to make contact with the transfer case. In other instances, the transfer case input shaft assembly may move axially approximately $\frac{1}{2}$ inch, shearing off or popping out the retaining rings.

Serial Numbers Affected

This product alert applies to all Canrig Commander™ Drawworks 2000, serial numbers 1 – 73.

Recommendation

Inspect gearbox (GB) and transfer case (TC) snap ring for damage or dislocation. Contact RIGLINE 24/7™ Support if problem found.



Figure 1: Gearbox and Transfer Case location on Drawworks 2000



Serial #: See Affected Units List

Alert

Procedure

Gearbox Input Shaft Assembly Inspection

- 1. Remove lube lines.
- 2. Open GB input shaft cover.
- 3. Check snap ring. If snap ring is damaged or popped out from groove, stop using drawworks and contact RIGLINE 24/7[™] Support immediately.
- 4. Ensure that TC Output Gear Shaft clamp has been installed. If not installed, contact RIGLINE 24/7[™] Support immediately.
- 5. Reinstall cover plate and lube line. Ensure that there are no oil leaks.






Figure 2: Gearbox input shaft assembly





RIGLINE 24/7™ Support Line: 866.433.4345 | International: +1 281.774.5649 | E-mail: support@rigline247.com Document ID 17-009 v 1.0 | Copyright © 2017 Canrig Drilling Technology Ltd. All rights reserved



Serial #: See Affected Units List

Alert

Gearbox Output Shaft Inspection

- 1. Remove lube lines.
- 2. Open GB output shaft cover.
- 3. Check snap ring. If snap ring is damaged or popped out from groove, stop using drawworks and contact RIGLINE 24/7[™] Support immediately.
- 4. Reinstall cover plate and lube line. Ensure that there are no oil leaks.




Figure 4: Gearbox Output Shaft




Figure 5: GB Output Shaft Schematic with Seal Detail. Snap Ring indicated.



Transfer Case Input Shaft Assembly Inspection

- 1. Remove lube lines.
- 2. Open TC input shaft cover.
- 3. Check snap ring. If snap ring is damaged or popped out from groove, stop using drawworks and contact RIGLINE 24/7[™] Support immediately.
- 4. Reinstall cover plate and lube line. Ensure that there are no oil leaks.




Figure 6: TC Shaft Assembly

