

Model: See Affected Equipment

Serial #: N/A

Product Bulletin # CDS-008

Nov. 19, 2021

Alert



# **ICDS Grapple Retention Retrofit Solution**

### Issue

An incident occurred in which two ICDS tool grapples came loose and fell to the rig floor. Canrig recommends the following course of action to prevent such incidents from occurring in the future.

# Affected Equipment

All the 12-3/4" to 16-3/4" ICDS tools regardless of the date of manufacture.

## **Background**

With the current 12-3/4" to 16-3/4" ICDS design, the grapples are required to be securely fastened when rotating while the grapples are NOT stabbed into the casing. Refer to the CDS Installation and Operations Guide – Document # 883003 (Currently Rev. 16 at the time this bulletin was published) for related Warnings and Information on when and how to securely fasten the grapples.

A dropped-object incident occurred directly caused by a malfunctioning top drive. During the troubleshooting, the top drive suddenly and unintentionally rotated at approximately 90 rpm while the grapples of the 18-5/8" ICDS tool were NOT stabbed into the casing. In these very rare conditions, the generated centrifugal force allowed the grapples to move away from the mandrel and collide with the CDS Links. As a result two heavily damaged grapples fell to the rig floor. There was no personnel injury.

12-3/4" to 16-3/4" ICDS tools and 18-5/8" ICDS tools share the same design.

A grapple retention retrofit solution is required to prevent a similar dropped-object incident under the same unusual conditions.




Serial #: N/A	2021
Model: See Affected Equipment	Nov. 19,

**Alert** 

# **Action Required**

Take the actions to retrofit the 12-3/4" to 16-3/4" ICDS tools by following the steps 1 to 7 below.

1. Dismantle the CDS – See Figure 1 and Figure 2 (Casing Stop Bumper and Collar and Spearhead Assembly not shown).



- Remove the Spearhead Assembly and Grapples from the CDS tool.
- Refer to the CDS Installation and Operations Guide Document # 883003 for instructions on how to remove the grapples.
- Determine the grapple serviceability:
  - Refer to the CDS Maintenance Guide Document # 883004 (Currently Rev. 17 at the time this bulletin was published).
- Disassemble the Mandrel from the CDS actuator and determine serviceability:
  - Refer to the CDS Maintenance Guide Document # 883004 for instructions on how to break-out the mandrel and determine serviceability.



**Alert** 

2. Modification of 'on-hand' Mandrel(s) – P/N: 15553 or 15553-1 – See Figure 3.




Figure 3

- Machine the slots, drill and thread the holes as per P/N: 5101754 Mandrel, 13-3/8" Modified for grapple retention.
- Refer to Appendix A for drawing 5101754.
- 3. Modification of 'on hand' Grapples (all grapple sizes 12-3/4" to 16-3/4") qty. 5 per set See Figure 4.




Figure 4

- If it is determined that the grapples are still serviceable, modify the grapples' rib as per P/N: 5101755 Grapple, 12-3/4" to 16-3/4", Modified for retention.
- Refer to Appendix B for drawing 5101755.



Model: See Affected Equipment	Nov. 19,	
Serial #: N/A	2021	
Alert		

• Grapples that qualify for modification/retrofit:

### Drawing # 80183202 Rev6 – 12-3/4" to 16-3/4" Casing

Ca	Part No.	
NOM. DIA	WEIGHT	ruii No.
13-3/8"	48.0–72.0 LB	15583
13-3/8"	68.0–102.0 LB	15584
16"	65–84 LB	17726
16"	96–118 LB	860121
16-3/4"	72.94–86.29 LB	5081711

- 4. Grapple Retainers Procurement
  - a. Procure P/N: 5101757 Kit, Grapple retention, 12-3/4" to 16-3/4" grapples from RIGLINE 24/7<sup>TM</sup>.

The kit includes the following parts:

### Grapple Retention Kit, 17-7/8" to 20" Grapples - Canrig P/N: 5101745


Item No.	Part No.	Qty.	Description
1	5101744	5	Retainer, Grapple, 12-3/4" to 16-3/4", ICDS
2	5040289	12*	Washer, Nord-Lock, 3/8"
3	3298	12*	Screw, Cap, Skt HD, 3/8"-16UNC x 3/4"
4	5101759	1	Wrench, Allen Bit Socket, 5/16" hex drive, 1/2" square drive

- \* Include 2 spares each
  - Refer to Appendix C for #5101757 Grapple Retention Kit drawing.




Nov. 19, 2021

### **Alert**



- 5. Assemble P/N: 5101744 Grapple Retainers (qty. 5) on the modified mandrel.
  - Refer to Figure 6 for the assembling detail.
  - Apply Loctite #243 to the screws.
  - Ensure the correct orientation of the Grapple Retainer.
  - Ensure the proper installation of the Nord-Lock washers.
  - Ensure the retainer is tight to the face of the pocket before the bolts are tighten. See Figure 6:





Model: See Affected Equipment
Serial #: N/A

Nov. 19, 2021

### **Alert**

- Use P/N: 50101759 Allen Bit Socket and appropriate Torque Wrench to tighten the screws to 43 ft-lb.
- 6. Re-assemble the Drive with modified mandrel to the actuator.
  - Refer to the CDS Maintenance Guide Document # 883004 for instructions on how to re-install the mandrel and other Drive components to the Actuator.
- 7. Install modified Grapples.
  - Refer to the CDS Installation and Operations Guide Document # 883003 for instructions on how to install the grapples.



**Warning!** When the modified grapples are stroked-in/retracted while the retrofit 12-3/4" to 16-3/4" ICDS is in horizontal position, ensure that the grapples positioned in the lower side are not moving away from the mandrel's ramps due to the gravity forces. Failure to maintain the lower side grapples close to the mandrel's ramps (in actuator release/open mode) may result in damage to the grapples and/or grapple retainers.



**Note:** The P/N: 5102566 – Grapple Retaining Strap – (see Figure 7), is required for retrofitted 12-3/4" to 16-3/4" ICDS tools.






Figure 7

Appendix A – P/N: 5101754 – Mandrel, 13-3/8", Modified for Grapple Retention



Appendix B – P/N: 5101755 – Grapple, 12-3/4" to 16-3/4", Modified for Retention



Appendix C - P/N: 5101757 - Grapple Retention Kit drawing

